
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	ned: Gwynns Falls Company: Savin	
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S05QQ_006MH	Test ID: <u>D1032-015005</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
10			Manhole	S05SS_006MH
222.5	11		Tap Break-in	From 2801 Chelsea
222.5			Dye Test Visible	@ TBI - roof leader
236			End of Survey	DYE TEST COMPLETED